

RG-IZP.271.6.2019

Dokumentacja fotograficzna ogrodzeń

kilometr	fotografia	uwagi
1155-1230	 A photograph showing a dirt road on the left, a wooden picket fence in the middle ground, and a brick house on the right. The area is overgrown with grass and weeds.	należy przewidzieć wykonanie nowych nasadzeń krzewów
	 A photograph showing a dirt road on the left, a wire fence in the middle ground, and a large tree on the right. A brick house is visible in the background.	

1255-1280






1345-1370




1570 - 1590





2100-2160



2200-2235



2405-2430



